## **Idaho PUC Pipeline Safety Inspection Summary**

Inspector(s):	Perkins		Date(s):	13-Jul-20
Company/Owner:	Intermed	untain Gas Company	Unit/OPID:	8160
company/owner:	intermot	untain Gas Company	onit/OPID.	8100
Inspection Type & Time (1	L day)	Total Ir	spection Days:	1
Standard: Construction:  M/M: Follow-up:	1 Training: OQ:	(T)(D) Integrity Management:  Damage Prevention:	Incident:	
Inspection Summary				
A construction inspection was performed on Das-co, a contractor for Intermountain Gas Company.				
13 Jul 2020: (1.0 Construction) Observed a Das-co crew installing a new %" service line at 6194 W Los Flores Dr, Meridian, Idaho. All procedures were followed. Typed up report  Areas observed during this project were: Excavating, line locating, backfilling, pressure testing and EFV test.  Attachments: IPUC Form 4 Construction Inspections Das-co daily Itineraries located in file for the project.  OQ's for all observed employees are located in file for the project.				
Corrective Action Required:		ow-up Required: Yes	L	X
Yes No	X		by (date):	
Inspector (Lead):  Bruce Perkins	Alicallo la		7/13/2020	
Reviewer:	M A	A.L.	Date:	
Darrin Ulmer	Narotta		lle Jul	0171